

10/22/01

Important Recall Notice

In cooperation with the U.S. Consumer Product Safety Commission the following BikeE models are subject to a voluntary recall:

2000 and 2001 E2 Tandem Bicycles

We have encountered three situations in which the steerer tube separated from the front fork crown. No injuries were incurred. If the steerer tube were to separate from the fork crown while riding you could lose control of your BikeE which could cause serious injury or death.

We ask that you immediately stop riding and bring your BikeE E2 tandem to your Authorized BikeE retailer for a no-charge recall service.



Picture of BikeE E2 Tandem

Resolving this problem is easy. If you have a BikeE E2 Tandem, contact your local BikeE dealers to schedule a fork replacement. Your dealer will install a new front fork at no charge.

We apologize for the problem and thank you for your cooperation.

Please call 1-800-231-3136 with any questions.

Sincerely,

BikeE Corporation
5125 SW Hout Street
Corvallis, OR 97333