

# Important Recall Notice

08/03/01

In cooperation with the U.S. Consumer Product Safety Commission the following BikeE models are subject to a voluntary recall:

**2000 and 2001 BikeE FX**

**2001 BikeE RX-Full Suspension**

We have encountered two situations in which the pins secured by set-screws holding the 2-bar linkage of the front suspension fork became loose and fell out. In both cases the riders sustained minor injuries. If these pins were to come out while you were riding you could lose control of your BikeE which could cause serious injury.



We ask that you immediately stop riding and bring your BikeE with front suspension to your Authorized BikeE retailer for a no-charge recall service.



Old Design



New Design

The fix is very simple and fast. Each linkage pin with a set-screw needs to be replaced with a linkage pin with a cir-clip. If you have a BikeE that may be affected by this recall, take your bike to your BikeE retailer for inspection. If your BikeE is affected, your dealer will install a new linkage kit that will include locking c-clips to insure your safety.

We apologize for the problem and thank you for your cooperation.

**Please call 1-800-231-3136 with any questions.**

Sincerely,

BikeE Corporation