

IMPORTANT RECALL NOTICE

Consumer Advisory

Cannondale is voluntarily recalling the POLYGON PM-215 seatpost used on the following Cannondale models. These seatposts have a clamping bolt which may crack without notice. If this bolt breaks in use you could lose control of your bicycle and be injured.

1994	4M300, 4M400, 4F400, Delta V 500, 4H300, 4H400, 4C600, 4T700, 4R600
1994 1/2	4.5F400, 4.5F500
1995	5M300, 5M400, 5M500, 5F500, 5F600, 5F200, Killer V 500, Super V 700, Super V 900, 5H300, 5H400, 5H600, 5T700, 5MT1000 (TANDEM)

If you have one of these models, please STOP RIDING YOUR BICYCLE IMMEDIATELY AND BRING IT TO YOUR CANNONDALE RETAILER FOR INSPECTION AND NO CHARGE REPLACEMENT OF THE BOLT AND CLAMPING MECHANISM.

If you are not sure if your bicycle is one of these models, please identify your bicycle with help from your Cannondale retailer.

If you have any questions about this recall please talk with your local Cannondale retailer or call Cannondale at 1-800-BIKEUSA (245-3872).

August 1994

cannondale
HANDMADE IN USA